

## STM32F413xG/xH and STM32F423xH device limitations

### Silicon identification

The STM32F413/423xx devices feature an ARM® 32-bit Cortex®-M4 core with FPU, for which an errata notice is also available (see [Section 1](#) for details).

The full list of part numbers is shown in [Table 2](#). The products are identifiable as shown in [Table 1](#):

- by the revision code marked below the order code on the device package
- by the last three digits of the Internal order code printed on the box label

**Table 1. Device identification<sup>(1)</sup>**

Order code	Revision code marked on device <sup>(2)</sup>
STM32F413xG/xH	A

1. The REV\_ID bits in the DBGMCU\_IDCODE register show the revision code of the device.
2. Refer to the device datasheet for details on how to identify the revision code and the date code on the different packages.

**Table 2. Device summary**

Reference	Part number
STM32F413xG/xH	STM32F413CG STM32F413MG STM32F413RG STM32F413VG STM32F413ZG STM32F413CH STM32F413MH STM32F413RH STM32F413VH STM32F413ZH
STM32F423xH	STM32F423CH STM32F423MH STM32F423RH STM32F423VH STM32F423ZH

# Contents

<b>1</b>	<b>ARM 32-bit Cortex-M4 with FPU limitations</b>	<b>5</b>
1.1	Cortex-M4 interrupted loads to stack pointer can cause erroneous behavior	5
1.2	VDIV or VSQRT instructions might not complete correctly when very short ISRs are used	6
<b>2</b>	<b>STM32F413/423xx silicon limitations</b>	<b>7</b>
2.1	System limitations	9
2.1.1	Debugging Sleep/Stop mode with WFE/WFI entry	9
2.1.2	Wakeup sequence from Standby mode when using more than one wakeup source	9
2.1.3	Full JTAG configuration without NJTRST pin cannot be used	10
2.1.4	MPU attribute to RTC and IWDG registers could be managed incorrectly	10
2.1.5	Delay after an RCC peripheral clock enabling	10
2.1.6	Internal noise impacting the ADC accuracy	11
2.1.7	In some specific cases, DMA2 data corruption occurs when managing AHB and APB2 peripherals in a concurrent way	11
2.2	IWDG peripheral limitation	12
2.2.1	RVU and PVU flags are not reset in STOP mode	12
2.3	I2C peripheral limitations	12
2.3.1	SMBus standard not fully supported	12
2.3.2	Start cannot be generated after a misplaced Stop	12
2.3.3	Mismatch on the "Setup time for a repeated Start condition" timing parameter	13
2.3.4	Data valid time ( $t_{VD;DAT}$ ) violated without the OVR flag being set	13
2.3.5	Both SDA and SCL maximum rise time ( $t_r$ ) violated when VDD_I2C bus higher than $((VDD+0.3) / 0.7)$ V	14
2.4	FMPI2C peripheral limitation	14
2.4.1	Wrong data sampling when data set-up time ( $t_{SU;DAT}$ ) is smaller than one FMPI2CCLK period	14
2.5	SPI peripheral limitation	15
2.5.1	Wrong CRC calculation when the polynomial is even.	15
2.5.2	BSY bit may stay high at the end of a data transfer in slave mode	15
2.5.3	Corrupted last bit of data and/or CRC, received in Master mode with delayed SCK feedback	16

2.6	USART peripheral limitations	17
2.6.1	Idle frame is not detected if receiver clock speed is deviated	17
2.6.2	In full duplex mode, the Parity Error (PE) flag can be cleared by writing to the data register	17
2.6.3	Parity Error (PE) flag is not set when receiving in Mute mode using address mark detection	17
2.6.4	Break frame is transmitted regardless of nCTS input line status	17
2.6.5	nRTS signal abnormally driven low after a protocol violation	18
2.6.6	Start bit detected too soon when sampling for NACK signal from the smartcard	18
2.6.7	Break request can prevent the Transmission Complete flag (TC) from being set	19
2.6.8	Guard time is not respected when data are sent on TXE events	19
2.6.9	nRTS is active while RE or UE = 0	19
2.7	bxCAN limitation	19
2.7.1	bxCAN time triggered communication mode not supported	19
2.8	FSMC peripheral limitation	20
2.8.1	Dummy read cycles inserted when reading synchronous memories	20
2.9	SDIO peripheral limitations	20
2.9.1	Wrong CCRCFAIL status after a response without CRC is received	20
2.9.2	No underrun detection with wrong data transmission	20
2.10	ADC peripheral limitations	21
2.10.1	ADC sequencer modification during conversion	21
2.11	DAC peripheral limitations	21
2.11.1	DMA underrun flag management	21
2.11.2	DMA request not automatically cleared by DMAEN=0	21
2.12	QUADSPI peripheral limitations	22
2.12.1	First nibble of data is not written after a dummy phase	22
<b>3</b>	<b>Revision history</b>	<b>23</b>

## List of tables

Table 1.	Device identification . . . . .	1
Table 2.	Device summary . . . . .	1
Table 3.	Cortex-M4 core limitations and impact on microcontroller behavior . . . . .	5
Table 4.	Summary of silicon limitations . . . . .	7
Table 5.	Maximum allowable APB frequency at 30 pF load . . . . .	16
Table 6.	Document revision history . . . . .	23

# 1 ARM 32-bit Cortex-M4 with FPU limitations

An errata notice of the STM32F413/423xx core is available from <http://infocenter.arm.com>.

All the described limitations are minor and related to the revision r0p1-v1 of the Cortex-M4 core. [Table 3](#) summarizes these limitations and their implications on the behavior of STM32F413/423xx devices.

**Table 3. Cortex-M4 core limitations and impact on microcontroller behavior**

ARM ID	ARM category	ARM summary of errata	Impact on STM32F413/423xx
752770	Cat B	Interrupted loads to SP can cause erroneous behavior	Minor
776924	Cat B	VDIV or VSQRT instructions might not complete correctly when very short ISRs are used	Minor

## 1.1 Cortex-M4 interrupted loads to stack pointer can cause erroneous behavior

### Description

An interrupt occurring during the data-phase of a single word load to the stack pointer (SP/R13) can cause an erroneous behavior of the device. In addition, returning from the interrupt results in the load instruction being executed an additional time.

For all the instructions performing an update of the base register, the base register is erroneously updated on each execution, resulting in the stack pointer being loaded from an incorrect memory location.

The instructions affected by this limitation are the following:

- LDR SP, [Rn],#imm
- LDR SP, [Rn,#imm]!
- LDR SP, [Rn,#imm]
- LDR SP, [Rn]
- LDR SP, [Rn,Rm]

### Workaround

As of today, no compiler generates these particular instructions. This limitation can only occur with hand-written assembly code.

Both limitations can be solved by replacing the direct load to the stack pointer by an intermediate load to a general-purpose register followed by a move to the stack pointer.

Example:

```
Replace LDR SP, [R0] by
LDR R2,[R0]
MOV SP,R2
```

## 1.2 VDIV or VSQRT instructions might not complete correctly when very short ISRs are used

### Description

On Cortex-M4 with FPU core, 14 cycles are required to execute a VDIV or VSQRT instruction.

This limitation is present when the following conditions are met:

- A VDIV or VSQRT is executed
- The destination register for VDIV or VSQRT is one of s0 - s15
- An interrupt occurs and is taken
- The ISR being executed does not contain a floating point instruction
- 14 cycles after the VDIV or VSQRT is executed, an interrupt return is executed

In this case, if there are only one or two instructions inside the interrupt service routine, then the VDIV or VSQRT instruction does not complete correctly and the register bank and FPSCR are not updated, meaning that these registers hold incorrect out-of-date data.

### Workaround

Two workarounds are applicable:

- Disable lazy context save of floating point state by clearing LSPEN to 0 (bit 30 of the FPCCR at address 0xE000EF34).
- Ensure that every ISR contains more than 2 instructions in addition to the exception return instruction.

## 2 STM32F413/423xx silicon limitations

Table 4 gives quick references to all documented limitations.

Legend for Table 4: A = workaround available; N = no workaround available; P = partial workaround available, '-' and grayed = fixed.

**Table 4. Summary of silicon limitations**

Links to silicon limitations		Revision A
Section 2.1: System limitations	<a href="#">Section 2.1.1: Debugging Sleep/Stop mode with WFE/WFI entry</a>	A
	<a href="#">Section 2.1.2: Wakeup sequence from Standby mode when using more than one wakeup source</a>	A
	<a href="#">Section 2.1.3: Full JTAG configuration without NJTRST pin cannot be used</a>	A
	<a href="#">Section 2.1.4: MPU attribute to RTC and IWDG registers could be managed incorrectly</a>	A
	<a href="#">Section 2.1.5: Delay after an RCC peripheral clock enabling</a>	A
	<a href="#">Section 2.1.6: Internal noise impacting the ADC accuracy</a>	A
	<a href="#">Section 2.1.7: In some specific cases, DMA2 data corruption occurs when managing AHB and APB2 peripherals in a concurrent way</a>	A
Section 2.2: IWDG peripheral limitation	<a href="#">Section 2.2.1: RVU and PVU flags are not reset in STOP mode</a>	A
Section 2.3: I2C peripheral limitations	<a href="#">Section 2.3.1: SMBus standard not fully supported</a>	A
	<a href="#">Section 2.3.2: Start cannot be generated after a misplaced Stop</a>	A
	<a href="#">Section 2.3.3: Mismatch on the "Setup time for a repeated Start condition" timing parameter</a>	A
	<a href="#">Section 2.3.4: Data valid time (tVD;DAT) violated without the OVR flag being set</a>	A
	<a href="#">Section 2.3.5: Both SDA and SCL maximum rise time (tr) violated when VDD_I2C bus higher than ((VDD+0.3) / 0.7) V</a>	A
Section 2.4: FMPI2C peripheral limitation	<a href="#">Section 2.4.1: Wrong data sampling when data set-up time (tSU;DAT) is smaller than one FMPI2CCLK period</a>	A
Section 2.5: SPI peripheral limitation	<a href="#">Section 2.5.1: Wrong CRC calculation when the polynomial is even.</a>	A
	<a href="#">Section 2.5.2: BSY bit may stay high at the end of a data transfer in slave mode</a>	A
	<a href="#">Section 2.5.3: Corrupted last bit of data and/or CRC, received in Master mode with delayed SCK feedback</a>	A

**Table 4. Summary of silicon limitations (continued)**

Links to silicon limitations		Revision A
Section 2.6: USART peripheral limitations	<a href="#">Section 2.6.1: Idle frame is not detected if receiver clock speed is deviated</a>	N
	<a href="#">Section 2.6.2: In full duplex mode, the Parity Error (PE) flag can be cleared by writing to the data register</a>	A
	<a href="#">Section 2.6.3: Parity Error (PE) flag is not set when receiving in Mute mode using address mark detection</a>	N
	<a href="#">Section 2.6.4: Break frame is transmitted regardless of nCTS input line status</a>	N
	<a href="#">Section 2.6.5: nRTS signal abnormally driven low after a protocol violation</a>	A
	<a href="#">Section 2.6.6: Start bit detected too soon when sampling for NACK signal from the smartcard</a>	A
	<a href="#">Section 2.6.7: Break request can prevent the Transmission Complete flag (TC) from being set</a>	A
	<a href="#">Section 2.6.8: Guard time is not respected when data are sent on TXE events</a>	A
	<a href="#">Section 2.6.9: nRTS is active while RE or UE = 0</a>	A
Section 2.7: bxCAN limitation	<a href="#">Section 2.7.1: bxCAN time triggered communication mode not supported</a>	A
Section 2.8: FSMC peripheral limitation	<a href="#">Section 2.8.1: Dummy read cycles inserted when reading synchronous memories</a>	N
Section 2.9: SDIO peripheral limitations	<a href="#">Section 2.9.1: Wrong CCRCFAIL status after a response without CRC is received</a>	A
	<a href="#">Section 2.9.2: No underrun detection with wrong data transmission</a>	A
Section 2.10: ADC peripheral limitations	<a href="#">Section 2.10.1: ADC sequencer modification during conversion</a>	A
Section 2.11: DAC peripheral limitations	<a href="#">Section 2.11.1: DMA underrun flag management</a>	A
	<a href="#">Section 2.11.2: DMA request not automatically cleared by DMAEN=0</a>	A
Section 2.12: QUADSPI peripheral limitations	<a href="#">Section 2.12.1: First nibble of data is not written after a dummy phase</a>	A



## 2.1 System limitations

### 2.1.1 Debugging Sleep/Stop mode with WFE/WFI entry

#### Description

When the Sleep debug or Stop debug mode is enabled (DBG\_SLEEP bit or DBG\_STOP bit are set in the DBGMCU\_CR register), this allows software debugging during Sleep or Stop mode. After wakeup some unreachable instructions could be executed if the following condition are met:

- If the application software disables the Prefetch queue
- The number of wait state configured on Flash interface is higher than 0
- And Linker place WFE or WFI instructions on 4-bytes aligned addresses (0x080xx\_xxx4)

#### Workaround

- Add three NOPs after WFI/WFE instruction
- Keep one AHB master active during sleep (example keep DMA1 or DMA2 RCC clock enable bit set)
- Execute WFI/WFE instruction from routines inside the SRAM

### 2.1.2 Wakeup sequence from Standby mode when using more than one wakeup source

#### Description

The various wakeup sources are logically OR-ed in front of the rising-edge detector which generates the wakeup flag (WUF). The WUF needs to be cleared prior to Standby mode entry, otherwise the MCU wakes up immediately.

If one of the configured wakeup sources is kept high during the clearing of the WUF (by setting the CWUF bit), it may mask further wakeup events on the input of the edge detector. As a consequence, the MCU might not be able to wake up from Standby mode.

#### Workaround

To avoid this problem, the following sequence should be applied before entering Standby mode:

- Disable all used wakeup sources,
- Clear all related wakeup flags,
- Re-enable all used wakeup sources,
- Enter Standby mode

*Note: Be aware that, when applying this workaround, if one of the wakeup sources is still kept high, the MCU enters Standby mode but then it wakes up immediately generating a power reset.*

### 2.1.3 Full JTAG configuration without NJTRST pin cannot be used

#### Description

When using the JTAG debug port in debug mode, the connection with the debugger is lost if the NJTRST pin (PB4) is used as a GPIO. Only the 4-wire JTAG port configuration is impacted.

#### Workaround

Use the SWD debug port instead of the full 4-wire JTAG port.

### 2.1.4 MPU attribute to RTC and IWDG registers could be managed incorrectly

#### Description

If the MPU is used and the non bufferable attribute is set to the RTC or IWDG memory map region, the CPU access to the RTC or IWDG registers could be treated as bufferable, provided that there is no APB prescaler configured (AHB/APB prescaler is equal to 1).

#### Workaround

If the non bufferable attribute is required for these registers, the software could perform a read after the write to guaranty the completion of the write access.

### 2.1.5 Delay after an RCC peripheral clock enabling

#### Description

A delay between an RCC peripheral clock enable and the effective peripheral enabling should be taken into account in order to manage the peripheral read/write to registers.

This delay depends on the peripheral's mapping:

- If the peripheral is mapped on AHB: the delay should be equal to 2 AHB cycles.
- If the peripheral is mapped on APB: the delay should be equal to  $1 + (\text{AHB/APB prescaler})$  cycles.

#### Workarounds

1. Use the DSB instruction to stall the Cortex-M4 CPU pipeline until the instruction is completed.
2. Insert "n" NOPs between the RCC enable bit write and the peripheral register writes ( $n = 2$  for AHB peripherals,  $n = 1 + \text{AHB/APB prescaler}$  in case of APB peripherals).

## 2.1.6 Internal noise impacting the ADC accuracy

### Description

An internal noise generated on  $V_{DD}$  supplies and propagated internally may impact the ADC accuracy.

This noise is always active whatever the power mode of the MCU (RUN or Sleep).

### Workarounds

To adapt the accuracy level to the application requirements, set one of the following options:

- Option1  
Set the ADCDC1 bit in the PWR\_CR register.
- Option2  
Set the corresponding ADCxDC2 bit in the SYSCFG\_PMC register.

Only one option can be set at a time.

For more details on option 1 and option2 mechanisms, refer to AN4073.

## 2.1.7 In some specific cases, DMA2 data corruption occurs when managing AHB and APB2 peripherals in a concurrent way

### Description

When the DMA2 is managing concurrent requests of AHB and APB2 peripherals, the transfer on the AHB could be performed several times.

Impacted peripheral are:

- **Quad-SPI:** indirect mode read and write transfers
- **FSMC:** read and write operation with external device having FIFO
- **GPIO:** DMA2 transfers to GPIO registers (in memory-to-peripheral transfer mode). The transfers from GPIOs register are not impacted.

The data corruption is due to multiple DMA2 accesses over AHB peripheral port impacting peripherals embedding a FIFO.

For transfer to the internal SRAM through the DMA2 AHB peripheral port the accesses could be performed several times but without data corruptions in cases of concurrent requests.

### Workaround

- The DMA2 AHB memory port must be used when reading/writing from/to Quad-SPI and FSMC instead of DMA2 AHB default peripheral port.
- The DMA2 AHB memory port must be used when writing to GPIOs instead of DMA2 AHB default peripheral port.

Refer to application note AN4031 section “Take benefits of DMA2 controller and system architecture flexibility” for more details about DMA controller feature.

## 2.2 IWDG peripheral limitation

### 2.2.1 RVU and PVU flags are not reset in STOP mode

#### Description

The RVU and PVU flags of the IWDG\_SR register are set by hardware after a write access to the IWDG\_RLR and the IWDG\_PR registers, respectively. If the Stop mode is entered immediately after the write access, the RVU and PVU flags are not reset by hardware.

Before performing a second write operation to the IWDG\_RLR or the IWDG\_PR register, the application software must wait for the RVU or PVU flag to be reset. However, since the RVU/PVU bit is not reset after exiting the Stop mode, the software goes into an infinite loop and the independent watchdog (IWDG) generates a reset after the programmed timeout period.

#### Workaround

Wait until the RVU or PVU flag of the IWDG\_SR register is reset before entering the Stop mode.

## 2.3 I2C peripheral limitations

### 2.3.1 SMBus standard not fully supported

#### Description

The I<sup>2</sup>C peripheral is not fully compliant with the SMBus v2.0 standard since it does not support the capability to NACK an invalid byte/command.

#### Workarounds

A higher-level mechanism should be used to verify that a write operation is being performed correctly at the target device, such as:

1. Using the SMBAL pin if supported by the host
2. the alert response address (ARA) protocol
3. the Host notify protocol

### 2.3.2 Start cannot be generated after a misplaced Stop

#### Description

If a master generates a misplaced Stop on the bus (bus error), the peripheral cannot generate a Start anymore.

#### Workaround

In the I<sup>2</sup>C standard, it is allowed to send a Stop only at the end of the full byte (8 bits + acknowledge), so this scenario is not allowed. Other derived protocols like CBUS allow it, but they are not supported by the I<sup>2</sup>C peripheral.

A software workaround consists in asserting the software reset using the SWRST bit in the I2C\_CR1 control register.

### 2.3.3 Mismatch on the “Setup time for a repeated Start condition” timing parameter

#### Description

In case of a repeated Start, the “Setup time for a repeated Start condition” (named  $T_{su;sta}$  in the I<sup>2</sup>C specification) can be slightly violated when the I<sup>2</sup>C operates in Master Standard mode at a frequency between 88 kHz and 100 kHz.

The limitation can occur only in the following configuration:

- in Master mode
- in Standard mode at a frequency between 88 kHz and 100 kHz (no limitation in Fast-mode)
- SCL rise time:
  - If the slave does not stretch the clock and the SCL rise time is more than 300 ns (if the SCL rise time is less than 300 ns, the limitation cannot occur)
  - If the slave stretches the clock

The setup time can be violated independently of the APB peripheral frequency.

#### Workaround

Reduce the frequency down to 88 kHz or use the I<sup>2</sup>C Fast-mode, if supported by the slave.

### 2.3.4 Data valid time ( $t_{VD;DAT}$ ) violated without the OVR flag being set

#### Description

The data valid time ( $t_{VD;DAT}$ ,  $t_{VD;ACK}$ ) described by the I<sup>2</sup>C standard can be violated (as well as the maximum data hold time of the current data ( $t_{HD;DAT}$ )) under the conditions described below. This violation cannot be detected because the OVR flag is not set (no transmit buffer underrun is detected).

This limitation can occur only under the following conditions:

- in Slave transmit mode
- with clock stretching disabled (NOSTRETCH=1)
- if the software is late to write the DR data register, but not late enough to set the OVR flag (the data register is written before)

#### Workaround

If the master device allows it, use the clock stretching mechanism by programming the bit NOSTRETCH=0 in the I2C\_CR1 register.

If the master device does not allow it, ensure that the software is fast enough when polling the TXE or ADDR flag to immediately write to the DR data register. For instance, use an interrupt on the TXE or ADDR flag and boost its priority to the higher level.

### 2.3.5 Both SDA and SCL maximum rise time ( $t_r$ ) violated when VDD\_I2C bus higher than $((V_{DD}+0.3) / 0.7)$ V

#### Description

When an external legacy I<sup>2</sup>C bus voltage (VDD\_I2C) is set to 5 V while the MCU is powered from V<sub>DD</sub>, the internal 5-Volt tolerant circuitry is activated as soon the input voltage (V<sub>IN</sub>) reaches the V<sub>DD</sub> + diode threshold level. An additional internal large capacitance then prevents the external pull-up resistor (R<sub>P</sub>) from rising the SDA and SCL signals within the maximum timing ( $t_r$ ) which is 300 ns in fast mode and 1000 ns in Standard mode.

The rise time ( $t_r$ ) is measured from V<sub>IL</sub> and V<sub>IH</sub> with levels set at 0.3VDD\_I2C and 0.7VDD\_I2C.

#### Workaround

The external VDD\_I2C bus voltage should be limited to a maximum value of  $((V_{DD}+0.3) / 0.7)$  V. As a result, when the MCU is powered from V<sub>DD</sub>=3.3 V, VDD\_I2C should not exceed 5.14 V to be compliant with I<sup>2</sup>C specifications.

## 2.4 FMPI2C peripheral limitation

### 2.4.1 Wrong data sampling when data set-up time (t<sub>SU;DAT</sub>) is smaller than one FMPI2CCLK period

#### Description

The I2C bus specification and user manual specifies a minimum data set-up time (t<sub>SU;DAT</sub>) at:

- 250ns in Standard-mode,
- 100 ns in Fast-mode,
- 50 ns in Fast-mode Plus.

The I2C SDA line is not correctly sampled when t<sub>SU;DAT</sub> is smaller than one FMPI2CCLK (FMPI2C clock) period: the previous SDA value is sampled instead of the current one. This can result in a wrong slave address reception, a wrong received data byte, or a wrong received acknowledge bit.

#### Workaround

Increase the I2CCLK frequency to get I2CCLK period smaller than the transmitter minimum data set-up time. Or, if it is possible, increase the transmitter minimum data set-up time

## 2.5 SPI peripheral limitation

### 2.5.1 Wrong CRC calculation when the polynomial is even.

**Description:**

When the CRC is enabled, the CRC calculation will be wrong if the polynomial is even.

**Work-around:**

Use odd polynomial.

### 2.5.2 BSY bit may stay high at the end of a data transfer in slave mode

**Description**

BSY flag may sporadically remain high at the end of a data transfer in Slave mode. The issue appears when an accidental synchronization happens between internal CPU clock and external SCK clock provided by master.

This is related to the end of data transfer detection while the SPI is enabled in Slave mode.

As a consequence, the end of data transaction may be not recognized when software needs to monitor it (e.g. at the end of session before entering the low-power mode or before direction of data line has to be changed at half duplex bidirectional mode). The BSY flag is unreliable to detect the end of any data sequence transaction.

**Workaround**

There are next possible workarounds in dependency on the SPI mode:

- When NSS hardware management is applied and NSS signal is provided by master, the end of a transaction can be detected by the NSS polling by slave.
- If SPI receiving mode is enabled, the end of a transaction with master can be detected by the corresponding RXNE event signaling the last data transfer completion.
- In SPI transmit mode, user can check the BSY under timeout corresponding to the time necessary to complete the last data frame transaction. The timeout should be measured from TXE event signaling the last data frame transaction start (it is raised once the second bit transaction is ongoing). Either BSY becomes low normally or the timeout expires when the synchronization issue happens.

When upper workarounds are not applicable, the following sequence can be used to prevent the synchronization issue at SPI transmit mode.

1. Write last data to data register
2. Poll TXE until it becomes high to ensure the data transfer has started
3. Disable SPI by clearing SPE while the last data transfer is still ongoing
4. Poll the BSY bit until it becomes low
5. The BSY flag works correctly and can be used to recognize the end of the transaction.

*Note: This sequence preventing the issue can be used only when CPU has enough performance to disable SPI after TXE event is detected while the data frame transfer is still ongoing. It is impossible to achieve it when ratio between CPU and SPI clock is low and data frame is short especially. In this specific case timeout can be measured from TXE, while calculating*

*fixed number of CPU clock periods corresponding to the time necessary to complete the data frame transaction.*

### 2.5.3 Corrupted last bit of data and/or CRC, received in Master mode with delayed SCK feedback

#### Description

In receive transaction, in both I2S and SPI Master modes, the last bit of the transacted frame is not captured when the signal provided by internal feedback loop from the SCK pin exceeds a critical delay. The lastly transacted bit of the stored data then keeps the value from the pattern received previously. As a consequence, the last receive data bit may be wrong and/or the CRCERR flag can be unduly asserted in the SPI mode if any data under check sum and/or just the CRC pattern is wrongly captured.

In SPI mode, data are synchronous with the APB clock. A delay of up to two APB clock periods can thus be tolerated for the internal feedback delay. The I2S mode is more sensitive than the SPI mode since the SCK clock is not synchronized with the APB. In this case, the margin of the internal feedback delay is lower than one APB clock period.

The main factors contributing to the delay increase are low VDD level, high temperature, high SCK pin capacitive load and low SCK I/O output speed. The SPI communication speed has no impact.

#### Workaround

The following workaround can be adopted, jointly or individually:

- Decrease the APB clock.
- Configure the IO pad of the SCK pin to be faster.

[Table 5](#) gives the maximum allowable APB frequency versus GPIOx\_OSPEEDR output speed control field setting for the SCK pin, at 30 pF of capacitive load.

**Table 5. Maximum allowable APB frequency at 30 pF load**

Setting of OSPEEDR bits [1:0] for the SCK pin	Maximum APB frequency for SPI [MHz]	Maximum APB frequency for I2S [MHz]
Very High (11)	100	84 (100 if V <sub>DD</sub> > 2.7 V)
High (10)	100	60
Medium (01)	80	30
Low (00)	28	14



## 2.6 USART peripheral limitations

### 2.6.1 Idle frame is not detected if receiver clock speed is deviated

#### Description

If the USART receives an idle frame followed by a character, and the clock of the transmitter device is faster than the USART receiver clock, the USART receive signal falls too early when receiving the character start bit, with the result that the idle frame is not detected (IDLE flag is not set).

#### Workaround

None.

### 2.6.2 In full duplex mode, the Parity Error (PE) flag can be cleared by writing to the data register

#### Description

In full duplex mode, when the Parity Error flag is set by the receiver at the end of a reception, it may be cleared while transmitting by reading the USART\_SR register to check the TXE or TC flags and writing data to the data register.

Consequently, the software receiver can read the PE flag as '0' even if a parity error occurred.

#### Workaround

The Parity Error flag should be checked after the end of reception and before transmission.

### 2.6.3 Parity Error (PE) flag is not set when receiving in Mute mode using address mark detection

#### Description

The USART receiver is in Mute mode and is configured to exit the Mute mode using the address mark detection. When the USART receiver recognizes a valid address with a parity error, it exits the Mute mode without setting the Parity Error flag.

#### Workaround

None.

### 2.6.4 Break frame is transmitted regardless of nCTS input line status

#### Description

When CTS hardware flow control is enabled (CTSE = 1) and the Send Break bit (SBK) is set, the transmitter sends a break frame at the end of the current transmission regardless of nCTS input line status.

Consequently, if an external receiver device is not ready to accept a frame, the transmitted break frame is lost.

**Workaround**

None.

**2.6.5 nRTS signal abnormally driven low after a protocol violation****Description**

When RTS hardware flow control is enabled, the nRTS signal goes high when data is received. If this data was not read and new data is sent to the USART (protocol violation), the nRTS signal goes back to low level at the end of this new data.

Consequently, the sender gets the wrong information that the USART is ready to receive further data.

On USART side, an overrun is detected, which indicates that data has been lost.

**Workaround**

Workarounds are required only if the other USART device violates the communication protocol, which is not the case in most applications.

Two workarounds can be used:

- After data reception and before reading the data in the data register, the software takes over the control of the nRTS signal as a GPIO and holds it high as long as needed. If the USART device is not ready, the software holds the nRTS pin high, and releases it when the device is ready to receive new data.
- The time required by the software to read the received data must always be lower than the duration of the second data reception. For example, this can be ensured by treating all the receptions by DMA mode.

**2.6.6 Start bit detected too soon when sampling for NACK signal from the smartcard****Description**

In the ISO7816, when a character parity error is incorrect, the Smartcard receiver shall transmit a NACK error signal at  $(10.5 \pm 0.2)$  etu after the character START bit falling edge. In this case, the USART transmitter should be able to detect correctly the NACK signal by sampling at  $(11.0 \pm 0.2)$  etu after the character START bit falling edge.

The USART peripheral used in Smartcard mode doesn't respect the  $(11 \pm 0.2)$  etu timing, and when the NACK falling edge arrives at 10.68 etu or later, the USART might misinterpret this transition as a START bit even if the NACK is correctly detected.

**Workaround**

None

## 2.6.7 Break request can prevent the Transmission Complete flag (TC) from being set

### Description

After the end of transmission of a data (D1), the Transmission Complete (TC) flag will not be set if the following conditions are met:

- CTS hardware flow control is enabled.
- D1 is being transmitted.
- A break transfer is requested before the end of D1 transfer.
- nCTS is de-asserted before the end of D1 data transfer.

### Workaround

If the application needs to detect the end of a data transfer, the break request should be issued after checking that the TC flag is set.

## 2.6.8 Guard time is not respected when data are sent on TXE events

### Description

In smartcard mode, when sending a data on TXE event, the programmed guard time is not respected i.e. the data written in the data register is transferred on the bus without waiting the completion of the guardtime duration corresponding to the previous transmitted data.

### Workaround

Write the data after TC is set because in smartcard mode, the TC flag is set at the end of the guard time duration.

## 2.6.9 nRTS is active while RE or UE = 0

### Description

The nRTS line is driven low as soon as RTSE bit is set even if the USART is disabled (UE = 0) or if the receiver is disabled (RE=0) i.e. not ready to receive data.

### Workaround

Configure the I/O used for nRTS as an alternate function after setting the UE and RE bits.

## 2.7 bxCAN limitation

### 2.7.1 bxCAN time triggered communication mode not supported

#### Description

The time triggered communication mode described in the reference manual is not supported. As a result timestamp values are not available. TTCM bit must be kept cleared in the CAN\_MCR register (time triggered communication mode disabled).

**Workaround**

None

## 2.8 FSMC peripheral limitation

### 2.8.1 Dummy read cycles inserted when reading synchronous memories

**Description**

When performing a burst read access to a synchronous memory, two dummy read accesses are performed at the end of the burst cycle whatever the type of AHB burst access. However, the extra data values which are read are not used by the FSMC and there is no functional failure.

**Workaround**

None.

## 2.9 SDIO peripheral limitations

### 2.9.1 Wrong CCRCFAIL status after a response without CRC is received

**Description**

The CRC is calculated even if the response to a command does not contain any CRC field. As a consequence, after the SDIO command IO\_SEND\_OP\_COND (CMD5) is sent, the CCRCFAIL bit of the SDIO\_STA register is set.

**Workaround**

The CCRCFAIL bit in the SDIO\_STA register shall be ignored by the software. CCRCFAIL must be cleared by setting CCRCFAILC bit of the SDIO\_ICR register after reception of the response to the CMD5 command.

### 2.9.2 No underrun detection with wrong data transmission

**Description**

In case there is an ongoing data transfer from the SDIO host to the SD card and the hardware flow control is disabled (bit 14 of the SDIO\_CLKCR is not set), if an underrun condition occurs, the controller may transmit a corrupted data block (with wrong data word) without detecting the underrun condition when the clock frequencies have the following relationship:

$$[3 \times \text{period}(\text{PCLK2}) + 3 \times \text{period}(\text{SDIOCLK})] \geq (32 / (\text{BusWidth})) \times \text{period}(\text{SDIO\_CK})$$

### Workaround

Avoid the above-mentioned clock frequency relationship, by:

- Incrementing the APB frequency
- or decreasing the transfer bandwidth
- or reducing SDIO\_CK frequency

## 2.10 ADC peripheral limitations

### 2.10.1 ADC sequencer modification during conversion

#### Description

If an ADC conversion is started by software (writing the SWSTART bit), and if the ADC\_SQRx or ADC\_JSQRx registers are modified during the conversion, the current conversion is reset and the ADC does not restart a new conversion sequence automatically.

If an ADC conversion is started by hardware trigger, this limitation does not apply. The ADC restarts a new conversion sequence automatically.

#### Workaround

When an ADC conversion sequence is started by software, a new conversion sequence can be restarted only by setting the SWSTART bit in the ADC\_CR2 register.

## 2.11 DAC peripheral limitations

### 2.11.1 DMA underrun flag management

#### Description

If the DMA is not fast enough to input the next digital data to the DAC, as a consequence, the same digital data is converted twice. In these conditions, the DMAUDR flag is set, which usually leads to disable the DMA data transfers. This is not the case: the DMA is not disabled by DMAUDR=1, and it keeps servicing the DAC.

#### Workaround

To disable the DAC DMA stream, reset the EN bit (corresponding to the DAC DMA stream) in the DMA\_SxCR register.

### 2.11.2 DMA request not automatically cleared by DMAEN=0

#### Description

if the application wants to stop the current DMA-to-DAC transfer, the DMA request is not automatically cleared by DMAEN=0, or by DACEN=0.

If the application stops the DAC operation while the DMA request is high, the DMA request will be pending while the DAC is reinitialized and restarted; with the risk that a spurious unwanted DMA request is serviced as soon as the DAC is re-enabled.

### Workaround

To stop the current DMA-to-DAC transfer and restart, the following sequence should be applied:

1. Check if DMAUDR is set.
2. Clear the DAC/DMAEN bit.
3. Clear the EN bit of the DAC DMA/Stream
4. Reconfigure by software the DAC, DMA, triggers etc.
5. Restart the application.

## 2.12 QUADSPI peripheral limitations

### 2.12.1 First nibble of data is not written after a dummy phase

#### Description

The first nibble of data to be written to the external Flash memory is lost in the following conditions:

- The QUADSPI is used in the indirect write mode
- And at least one dummy cycle is used

#### Workaround

Use alternate-bytes instead of a dummy phase in order to add a latency between the address phase and the data phase. This works only if the number of dummy cycles corresponds to a multiple of 8 bits of data.

Example:

To generate:

- 1 dummy cycle: send 1 alternate-byte, possible only in 4 data line DDR mode or Dual-flash SDR mode
- 2 dummy cycles: send 1 alternate-byte in 4 data line SDR mode
- 4 dummy cycles: send 2 alternate-bytes in 4 data line SDR mode or send 1 alternate-byte in 2 data line SDR mode
- 8 dummy cycles: send 1 alternate-byte in 1 data line SDR mode

### 3 Revision history

**Table 6. Document revision history**

Date	Revision	Changes
12-Oct-2016	1	Initial release.
21-Nov-2016	2	Changed confidentiality level from ST Restricted to Public. Updated: – <a href="#">Table 4: Summary of silicon limitations</a> – <a href="#">Section 2.5.2: BSY bit may stay high at the end of a data transfer in slave mode</a> – <a href="#">Section 2.5.3: Corrupted last bit of data and/or CRC, received in Master mode with delayed SCK feedback</a> Added: – <a href="#">Table 5: Maximum allowable APB frequency at 30 pF load</a>

**IMPORTANT NOTICE – PLEASE READ CAREFULLY**

STMicroelectronics NV and its subsidiaries ("ST") reserve the right to make changes, corrections, enhancements, modifications, and improvements to ST products and/or to this document at any time without notice. Purchasers should obtain the latest relevant information on ST products before placing orders. ST products are sold pursuant to ST's terms and conditions of sale in place at the time of order acknowledgement.

Purchasers are solely responsible for the choice, selection, and use of ST products and ST assumes no liability for application assistance or the design of Purchasers' products.

No license, express or implied, to any intellectual property right is granted by ST herein.

Resale of ST products with provisions different from the information set forth herein shall void any warranty granted by ST for such product.

ST and the ST logo are trademarks of ST. All other product or service names are the property of their respective owners.

Information in this document supersedes and replaces information previously supplied in any prior versions of this document.

© 2016 STMicroelectronics – All rights reserved